

Work Order ID 73589

Tuesday, September 06, 2011 11:08:42 AM



Ship xpt 1/2

Page 1

Item ID: D350-721-046

Accept



Setup Start



Revision ID:

Item Name: Maintenance Step, RH

Stop



Start Date: 9/6/2011 Start Qty: 1.00



Cust Item ID:

Required Date: 9/12/2011 Req'd Qty: 1.00



Customer:

Reference:

Approvals: Process Plan: *ME* Date: *11-09-0*

Tooling:

Date:

Run Start



QC:

Date:

SPC (Y/N):

Date:

Stop



Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
--------------------------------	--------------------------	----------------------	---------	--------	--------------	---------------	---------------	------------------	----------------

Draw Nbr	Revision Nbr
----------	--------------

IIN-D350-721	Rev b
--------------	-------

100	DOCUMENT CONTROL	0.00
-----	------------------	------



DC

Memo

0.00

Document Control

Photocopy bluefile and create labels per PPP D350-721-046 CHG001

Sulab

11-9-11 MF

110	Pick Kit	0.00
-----	----------	------



Packaging

Memo

0.00

Packaging

11/9/11

120	QC4- 100% Inspect kits for completeness	0.00
-----	---	------



QC

Memo

0.00

Quality Control

Sulab

70

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Work Order ID 73589

Tuesday, September 06, 2011 11:08:42 AM




Page 2

Item ID: D350-721-046

Accept



Setup Start



Revision ID:

Item Name: Maintenance Step, RH

Stop



Start Date: 9/6/2011 Start Qty: 1.00



Cust Item ID:

Required Date: 9/12/2011 Req'd Qty: 1.00



Customer:

Reference:

Approvals: Process Plan: _____ Date: _____ Tooling: _____ Date: _____

QC: _____ Date: _____ SPC (Y/N): _____ Date: _____

Run Start



Stop



Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
130 	Packaging	0.00							
Packaging	Memo	0.00							
Packaging	Identify and pack for shipping as per PPP D350-721-046 Identify and Stock Location: <u>22</u> R40A								
140 	QC21- Final Inspection - Work Order Release	0.00							
QC	Memo	0.00							
Quality Control									

11/9/17

11/9/17

MF 11-09-07

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Picklist Print

Tuesday, September 06, 2011 11:08:36 AM

Page 1

Work Order ID: 73589

Parent Item: D350-721-046

Parent Item Name: Maintenance Step, RH

Start Date: 9/6/2011

Required Date: 9/12/2011

Start Qty: 1.00

Required Qty: 1.00

Comments: IPP A 05.05.11 New Issue KJ/JLM
IPP B 07.10.10 removed D3436-041 EC verified by DD

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
---------------------------------	------------------------	---------------	-------------	---------------------	------------------	-----------------	--------------------	----------------	-------------	--------------	---------------	----------------	--------

AN4-16A Bolt		Purchased	No			120	Each	106.0000	4	4			
-----------------	--	-----------	----	--	--	-----	------	----------	---	---	--	--	--

Location Loc Qty Loc Code

ST358 106
117514 6
117872 100

Reste 5 autre

AN960-416 Washer	NAS1149F0463P	Purchased	No			120	Each	0.0000	8	8			
---------------------	---------------	-----------	----	--	--	-----	------	--------	---	---	--	--	--

D3436-044 Step RH		Manufactured	No			120	Each	0.0000	1	1			
----------------------	--	--------------	----	--	--	-----	------	--------	---	---	--	--	--

MS20365-428 NUT		Purchased	No			120	Each	37.0000	4	4			
--------------------	--	-----------	----	--	--	-----	------	---------	---	---	--	--	--

Location Loc Qty Loc Code

ST315 37
116391 37

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries


6.0 PARTS LIST

Qty -011	Qty -041	Qty -043	Qty -045	Qty -046	PART NUMBER	DESCRIPTION
X					D350-721-011	BASKET CLAMP KIT
	X				D350-721-041	LIGHTWEIGHT HELI- UTILITY-BASKET™
		X			D350-721-043	LIGHTWEIGHT HELI-UTILITY-BASKET™, SHORT VERSION
			X		D350-721-045	MAINTENANCE STEP, LH
				X	D350-721-046	MAINTENANCE STEP, RH
	1				D3324-041	BASKET BASE ASSEMBLY
	1				D3325-041	BASKET LID ASSEMBLY
		1			D3326-041	BASKET BASE ASSEMBLY
		1			D3327-041	BASKET LID ASSEMBLY
	2	2			D2022-101	SPACER
3	3	3			D2230-1	LUG
4	4	4			D2230-3	CLAMP
	1	1			D2332-041	PROP ASSEMBLY
	1	1			D2530	HANDLE ASSEMBLY
	2	2			D2535	SPRING
	2	2			D2537	BUSHING
8	8	8			D2732-030	RUBBER CUSHION
	2	2			D2931	BUMPER
	1	1			D3338-1	LUG
	2	2			D3350-041	STRUT
	1	1			D3351-1	LABEL
			1	1	D3436-041	CLAMP
			1		D3436-043	LH STEP
				1	D3436-044	RH STEP
	2	2			AN3-16A	BOLT
	2	2			AN4-7A	BOLT
	2	2			AN4-12A	BOLT
	4	4			AN4-14A	BOLT
8	8	8			AN4-15A	BOLT
			4	4	AN4-16A	BOLT
	1	1			AN4-20A	BOLT
	1	1			AN4-22A	BOLT
	4	4			AN5-17A	BOLT
			8	8	AN960-416	WASHER
16	30	30			AN960JD416	WASHER
	2	2			AN960JD416L	WASHER
	4	4			AN960JD516	WASHER
	2	2			AN960JD8	WASHER
	4	4			AN970-4	WASHER
			4	4	MS20365-428	NUT
	2	2			MS20600AD4W3	RIVET
	2	2			MS21042L3	NUT (OR MS21042-3)
8	18	18			MS21042L4	NUT (OR MS21042-4)
	4	4			MS21042L5	NUT (OR MS21042-5)

REFERENCE ONLY



DESIGN MB	DRAWN BY MB	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
CHECKED <i>[Signature]</i>	APPROVED <i>[Signature]</i>	DRAWING NO. D3436	REV. A SHEET 1 OF 4
DATE 05.04.28	TITLE MAINTENANCE STEP		SCALE 1:4
A	05.04.28	NEW ISSUE	



NOTES:

- 1) POSITION PARTS AS PER JIGS DT8772 AND DT8773
- 2) WELD PER DART QSI 004
- 3) FILLET BOTH TOP AND BOTTOM EDGES OF CLAMP ALONG 2.38 I.D. SECTION TO 0.03 RADIUS TO PREVENT SCORING AND SCRATCHING OF SKID CROSS TUBE
- 4) FINISH: POWDER COAT WHITE GLOSS (4.3.5.2) PER DART QSI 005 4.3
- 5) APPLY BLACK ANTI-SKID PAINT AS SHOWN PER DART QSI 005 4.4
- 6) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED
- 7) ALL DIMENSIONS ARE IN INCHES

COPYRIGHT © 2005 BY DART AEROSPACE LTD.

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.